



FG6890G01 Firmware Update v02.03 Readme

After the firmware update the FG6890G01 will detect a mismatch of the new firmware version and the firmware version stored in the configuration file of the FG6890G01. This mismatch results in a warning.



To resolve this warning a new configuration file must be generated and uploaded to the FG6890G01. The following steps must be performed to generate the new configuration:

<p>Open the configuration download page and press the Generate & apply button</p>	
<p>You will be forwarded to the configuration upload page. In the Status column POS1 and system have status Unchanged, cause only the version number will be updated.</p> <p>Press the Apply config button</p>	

<p>Activate the Select all boards check box and then press the Reboot button to perform the configuration upload</p>	
<p>After the following reboot the warning is resolved</p>	