

FG8801N02 Firmware Release Notes

Firmware Version	Changes
v0200	SIMATIC time service can now be configured for two broadcast addresses Events and alarms are forwarded to the management board for distribution Improved synchronization Improved bus communication
v0106	Bugfix: Fixed synchronisation issue
v0104	First released firmware version